

## CENTRAL INTELLIGENCE AGENCY

## INFORMATION REPORT

SECRET/CONTROL - U. S. OFFICIALS ONLY

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

617850

COUNTRY	Poland	REPORT		25X1
SUBJECT	Kedzierzyn Chemical Plant	DATE DISTR.	26 April 1954	
		NO. OF PAGES	4	
DATE OF INFO.		REQUIREMENT NO.	RD	
PLACE ACQUIRED				25X1

This is UNEVALUATED Information

THE SOURCE EVALUATIONS IN THIS REPORT ARE DEFINITIVE.  
THE APPRAISAL OF CONTENT IS TENTATIVE.  
(FOR KEY SEE REVERSE)

1. In spite of the large labor force employed in the construction of the chemical combine at Kedzierzyn (Heydebreck), the work advances slowly. This is due to the shortage of materials, cement in particular, a lack of which holds up entire gangs of workers at times. The Chief Director of the building combine at present is Spiess (fnu), a former fitter by trade, who came from Upper Silesia. 25X1
2. The main boiler house(Point 21 on Sketch) is being rebuilt and is nearing completion. The high pressure boilers of 60 atm. are to be supplied by Austria. 25X1  
Two have already been delivered and installed.
3. The large fuel storage area (Point 3 on Sketch), covering an area of 800 m. x 400 m., was probably the former synthetic gasoline plant's reserve store. The various tanks are located underground; only mounds of earth and concrete entrances are visible.
4. 25X1  
constant loading and unloading of fuel from and into railroad tank cars. the fuel was destined for Wroclaw and Nowa Huta. Fuel is not being produced at the plant.
5. The following work is in progress at the combine:
  - a. In the "Monta-Chem", an independent plant:
    - Lathes
    - Lathes with horizontal face plates
  - b. In the electrical department of "Monta Chem":
    - Extent of production and destination not known 25X1
  - c. In the annex to the large laboratory:
    - Artificial fertilizers
    - Soft soap

25 YEAR RE-REVIEW

SECRET/CONTROL - U. S. OFFICIALS ONLY

STATE	X	ARMY	X	NAVY	X	AIR	X	FBI		AEC						
-------	---	------	---	------	---	-----	---	-----	--	-----	--	--	--	--	--	--

(Note: Washington Distribution Indicated By "X"; Field Distribution By "#".)

SECRET/CONTROL - U. S. OFFICIALS ONLY

-3-

25X1

## Legend

1. Administration building
2. Main garage of the combine
3. Fuel storage and filling station
4. Large laboratory
5. Annex (workshop) in which soft soap is produced
6. Annex (workshop) in which artificial fertilizer is produced
7. Damaged premises (Anlage); no steps being taken for reconstruction
8. Boiler house No. 1 (2 boilers of 4 atm); produces steam for requirements of the oxygen plant, for heating the Administration building and the main garage
9. Fire Station of the combine. The fire engines are parked in the main garage, however
10. Coal storage
11. Factory premises under construction; demolition and building work in progress. Synthetic gasoline was formerly produced here. It is alleged that the installations are to be set up again.
12. One-story store room for oxygen flasks
13. General stores
14. Water reservoir of the combine, in case of an emergency, and water repair workshop. The reservoir is only partly in operation (4 tanks); the other tanks are damaged and are not being repaired at present.
15. Small laboratory (newly constructed, one-story building): used exclusively for experimental work
16. Damaged factory premises
17. Boiler house No. 2 (3 low pressure boilers of 7 atm.); supplies steam for production at the large laboratory (Point 4 on sketch), small laboratory (Point 15 on sketch) and for the "Monta Chem" plant (Point 23 on sketch)
18. Area with ruined factory premises; clearing work is in progress
19. Electro plant with workshop for training apprentices. Electrical measuring instruments and thermostats are produced here. Electro repairs are executed in the workshop for trainees.
20. Oxygen plant; in operation
21. Main boiler house of the combine; under construction
22. Distillation plant; partly damaged and fallen into decay
23. The "Monta Chem" plant.

SECRET/CONTROL - U. S. OFFICIALS ONLY

**SECRET/CONTROL - U. S. OFFICIALS ONLY**

**-2-**



25X1

d. In the electro plant:

Electrical measuring instruments

Thermostats

Production details not known



25X1

e. In the oxygen plant:

Oxygen. The flasks for the oxygen are stored in location 12 on the sketch and despatched from here.


**SECRET/CONTROL - U. S. OFFICIALS ONLY**

SECRET/CONTROL - U.S. OFFICIALS ONLY

-4-

25X1

Kedzierzyn Chemical Plant



SECRET/CONTROL - U.S. OFFICIALS ONLY